



Technical Bulletin

HyNet™ Gateway Firmware Release: h2.10

PRODUCT: HyNet Gateway

DATE: 04/23/2021

SUBJECT: New h2.10 Firmware Release (Filename: HyNeth210.hyn.exe)

SUBJECT DESCRIPTION:

New HyNet firmware h2.10 has been released.

CONTENT:

New features, enhancements, and fixes.

FIELD PROGRAMMING DEVICE:

Ethernet Connection or MicroSD Card

New Features:

- Added extended event log to capture Hy5B sensitivity.

Changes/Enhancements:

- Added Error 15 and logs for loading of all CNX boards.
- Added Fault 9 to log for CNX boards.
- Updated company address and copyright dates.
- Added logging of active sensor if gate motion is interrupted.
- Removed the need to enter license number during setup:
 1. updated INFO pop-up
 2. Removed ENTER LICENSE KEY from setup drop-down menu

Fixed Issues:

- Extended the “Open gate before loading software” checkbox timeout from 10 secs to 20 secs to allow for slower gates when auto-opening before a software update over the network connection.

Download File Hyneth2.10.exe:

<https://support.hysecurity.com/hc/en-us/articles/360043785494>

Contact Information:

Visit <https://support.hysecurity.com/hc/en-us> for installation manuals, replacement part instructions, part diagrams and more. Qualified HySecurity distributors are experienced and trained to assist in resolving installation problems. For the name of a qualified distributor near you, call HySecurity at 800-321-9947. *Before contacting your distributor or HySecurity Technical Support, obtain the serial number of your operator.