

NEW PhotoEye Retrofit Kit for StrongArm M30-M50

SUBJECT: New photoeye retrofit kit

DATE: 03/05/2024

PRODUCTS AFFECTED: M30 and M50 StrongArm Operators

IMPACT: Change to enclosure part numbers and sizing, but features, function, and wiring unchanged

A new photoeye retrofit kit (P/N MX5803) has been released for use on M30 and M50 StrongArm Crash operators. The original photoeye (MX3990) is now obsolete, and this kit replaces the existing brackets and hardware to accommodate the new photoeye (MX5792-02) in existing Strong Arm Crash Operators.

Instructions:

1. Discard any old parts (see FIG-2, MX4290, MX4293, & MX3990).
2. Replace with new MX5803 kit parts (see FIG-1, MX5786, MX5787, & MX5792-02).
3. Wire photoeye the same as previously wired.




FIG-1: P/N MX5803, NEW PhotoEye Enclosure Kit




FIG-2: Old Obsolete Parts to Discard



Technical Bulletin
