

### New and Improved LED Lights on Arm of the StrongArmCrash (M30/M50) Products

HySecurity has improved the barrier arm LED lights for all powered StrongArmCrash (M30/M50) products manufactured after 06/24/2019. The new LEDs are brighter and offer better consistency across the barrier arm. The old LED lights are no longer available. Replacing arms and lights on older gates requires new hardware available in a retrofit kit (P/N MX4671-XX).

**OPERATORS:** All StrongArmCrash (M30/M50) products

**DATE:** 08/28/2019

**EFFECTIVITY DATE:** 06/24/2019

**EFFECTIVITY SERIAL#:** All serial numbers AFTER the following feature the new LED lights:

- 6AC458-1923-169 (StrongArm M30)
- 6EB657-1925-278 (StrongArm M50)

**IMPACT:** Replacing an arm or the LED lights on an older gate requires a one time upgrade using different cables, hardware, and power supply. HySecurity has created a retrofit kit including all the required components and parts:

- Retrofit kit P/N MX4671-01 will retrofit arms of 18 feet or shorter.
- Retrofit kit P/N MX4671-02 will retrofit arms of 18 feet or longer.

To determine if a gate has already been upgraded to the new LED lights, refer to the following images:

