




4000 Swing

Part Diagrams

4300/4500 Arm



This drawing is a representation and should be used for parts reference only.

4000 Swing

Part Diagrams



4300/4500 Chassis with Control Board

Part Name	Part Number	4000 Models
Arm Assembly, 4300/4500	ABOX4SW	all
Board, Control, 1050	1050US	all
Cover, Front	PPD2262	all
Cover, Rear	PPD2263SW	all
Limit Switch Kit	SPLSM00300	all
Lock and Key	SPREG00300	all
Motor Gearbox, 1/2 hp and 1 hp Motors	SPAMG039B00	all
Motor Kit, 1 hp	NAKM001	all
Motor Kit, 1/2 hp	NAKM002	all
Power Supply	NCO-PWRSUP	all
Rain Ring, Plastic Drip	PPD2265R02-4540	all
Switch Box	10055710	all
Toriod Kit	SPEG001A00A	all