

# Technical Bulletin

## New Firmware H6.08 and H6.09

**SUBJECT:**

Nice is releasing new firmware for the SmartTouch 725.

**DATE:** 10/2025

**OPERATORS:**

SlideDriver II

HydraSupply II used with HydraSwing, SwingRiser, and Modular SlideDriver

SwingSmart 535

SlideSmart 535

All operators using the SmartTouch 720 and 725 Controllers

**DESCRIPTION:**

Firmware version h6.08 and h6.09 are released for use with the SmartTouch Controller.



**Note:** These firmware versions are not compatible with the SmartCNX Drive Module (MX4285, AKA MX5185). To operate the SmartCNX Drive module the controller must run h6.07. This software may be loaded on a SmartCNX operator only if equipped with the SmartBLDC drive module.



**Note:** Loading firmware over h6.03 requires the USB drive to be left in the operator after the initial firmware load as second update occurs automatically to load the Web Server firmware.

**h6.08 Key Updates**

- Supports HydraSupply II SwingRiser and HydraSwing operator solutions
- Improves limit sensing on SlideDriver II Model SD50F
- Added support for hydraulic pressure diagnostics in HyNet
- Fixed intermittent OXI communication reliability issue

**h6.09 Key Updates**

- Supports Smart535 Operators with SmartBLDC Power Module
- Improved solar performance/standby current (only on Rev. D Control Boards)
- Updated link to HyNet™ user manual within HyNet™ embedded interface