

TECHNICAL BULLETIN

SmartCNX[™] h6.00 to h6.05 Firmware Update

DATE: 09/01/2021

1

OPERATORS: SwingSmartCNX[™] and SlideSmartCNX[™]

SUBJECT: Updating firmware from version H6.00 to H6.05

PROBLEM:

When updating a SmartCNX controller from firmware version H6.00 directly to H6.05 (or later) there is a bug which causes the controller to display the error "Unable to Read" and the firmware update to be unsuccessful.

SOLUTION:

First update the controller to firmware version H6.03, and then update to version H6.05 or later.

NOTICE

Only one firmware version should be on the USB flash drive at a time.

LINKS:

The firmware files can be downloaded from the support centre here:

https://support.hysecurity.com/hc/en-us/sections/360007535934-HySecurity-Software-and-Installer-Appfor-SmartCNX

The tech bulletins for each firmware version (including update instructions) can be found here: https://support.hysecurity.com/hc/en-us/sections/360007235893-Tech-Bulletins-HySecurity-Products

A USB drive with the latest firmware pre-loaded can be purchased from Nice | HySecurity under part number MX5013 (this will contain only the latest CNX Firmware).

NOTICE

HySecurity always recommends installing the latest firmware on all gate operators, this ensures the most reliable and up to date features are present.

Contact Information: Visit https://support.hysecurity.com/hc/en-us for installation manuals, replacement part instructions, part diagrams and more. Qualified HySecurity distributors are experienced and trained to assist in resolving installation problems. For the name of a qualified distributor near you, call HySecurity at 800-321-9947. *Before contacting your distributor or HySecurity Technical Support, obtain the serial number of your operator.

support.hysecurity.com D1099 Rev. A ©2021